



febiEXAKT



DPF Pressure Hose

febi no. 45777

OE No. 1 440 559, 6G915H241AA

to fit

Ford Mondeo 07 / S-Max 06 /

Galaxy 06 with 2.0 TDCi engine



>> PROBLEM:

The "Diesel Particulate Filter" (DPF) icon is displayed on the digital instrument panel.

>> CAUSE:

In the Ford models mentioned above, a pressure hose which routes the exhaust gas pressure to a differential pressure sensor is located on the DPF. If the differential pressure upstream and downstream of the filter is too high, this is a sign that the filter is saturated and needs replacing.

It may be that the pressure hose is blocked or has been scorched by the high temperatures, causing it to leak. As a result, the pressure actually prevailing at the differential pressure sensor is transmitted incorrectly or not at all. In this case, the engine control unit receives incorrect information and passes it on to the driver via the warning light.

In most cases, diagnosis in the workshop reveals that the differential pressure sensor is faulty and requires replacing.

>> SOLUTION:

Check the lines and hoses of the diesel particulate filter or sensor before carrying out a costly replacement.

The problem is often remedied simply by replacing the pressure hose. This saves the vehicle owner an expensive repair.



Register now for the official febi bilstein newsletter and receive the latest technical information automatically by email!

Further information may be obtained at: www.febi.com