


NUMBER 013

21/04/2006



Renault 1.5 DCI / Accessory drive / Installation Info.

GATES REFERENCE: | Accessory drive belt

MAKE: RENAULT

MODEL: Clio II, Express, Kangoo, Rapid, Symbol

MOTOR: 1.5 DCI

MOTOR CODE: K9K700, K9K702, K9K710



Certain Renault 1.5 dCi models, produced between June 2001 and June 2002, **without air-conditioning**, could have issues with the accessory drive belt, as a result of tensioner problems.

The tensioner base plate could deform, resulting in misalignment, belt noise and early failure.

In order to cure this, Renault launched a technical note, saying the old tensioner (OE ref. 8200262773, 8200292784) together with the 2 tensioner bolts (torx-head) as well as the accessory drive belt (OE ref. 8200020924) have to be replaced.

Vehicles involved:

*Clio II, Symbol, Van 1.5DCi. Chassis codes: BB07, BB08, CB07, CB08, LB07, SB07, SB08; with engine K9K700 or K9K702.

*Kangoo, Rapid, Express 1.5DCI. Chassis codes: FC07, FC08, KC07, KC09; with engine K9K700, K9K702 or K9K710.

How to proceed:

- 1. Loosen the tensioner bolts.
- 2. Remove the accessory drive belt.
- 3. Remove the tensioner bolts and tensioner.
- 4. Install the new tensioner (OE ref. 8200328372).
- 5. Use 2 new bolts (OE ref. 7703002059 hex head).
- 6. Install the 2 bolts hand tight.
- 7. Install a new Micro-V[®] belt 5PK1133 (OE ref. 8200020924).

Attention!


The pulleys of this drive have 6 grooves, while the prescribed belt only has 5 ribs. The groove closest to the engine bloc has to remain free.

8. Tension the belt: the belt has to be tensioned (with tool Mot.1638, OE ref. 0000163800) to a higher tension than with the original drive set-up. Measure the tension in the bottom span, between the crankshaft and power steering pump (or idler for cars without power steering) (Fig.1).



NUMBER 013

21/04/2006






Fig. 1

- 9. When measuring the belt tension with the STT-1, key in "8", "180" (virtual span of 180 mm). When measuring with the Krikit[®], tension has to be 70 Kg.
- 10. Now tighten both bolts (36 Nm).
- 11. Rotate the engine 2 revolutions clockwise.
- 12. Check the tension and adjust if needed.
- 13. Re-install all removed parts.

visit our web catalogue: http://www.gatesautocat.com