

# Previous Technical Bulletins

## CL 034 Damaged Drive Plate

Vehicles: All Models

The Valeo Service Warranty Department have received Conversion Kits & DMF Module Kits (clutch & flywheel that are sold together in the same kit), where damage has been inflicted on the clutch plate and it cannot be used. After investigating, the damage caused has been traced to the clutch friction plate coming into contact with the locating dowels on the flywheel.

This issue will occur if the kit is not transported correctly.

Valeo clutch kits sold with flywheels **MUST ALWAYS** be transported and stored horizontally. If the kit is transported vertically, the clutch cover could become detached from the flywheel and allow the drive plate to move between the two parts.



Image showing how clutch plate becomes damaged from locating dowels on flywheel