

Cooling



FWP 1574



FWP 1574 fits vehicles with a 23 tooth pulley.

It is important to check this is the correct part before fitting to the vehicle.

If the incorrect pump is fitted then timing belt failure will occur soon after installation resulting in damage to the cylinder head and valve gear.



www.firstline.co.uk