



All you need for professional repairs

The most frequent cause for windscreen wiper motors to fail is the motor overheating or rotating too much. Also, age-related wear can lead to the wiper linkage binding.

Since the wiper motor has no threaded holes, in order to replace it, usually additional self-tapping screws have to be sourced.

febi bilstein offers a complete solution unique on the aftermarket under part number febi 38800:

Windscreen wiper motor with fitting materials



febi no. 38800

Repl. no. 6405.N5

Fits:

Peugeot 206 (1998 – 2006)

Peugeot 206 SW (2002 – 2007)

Peugeot 206 CC (2000 – 2007)

Peugeot 206 + (2009 –)



Attention!

febi bilstein recommends testing the ease of movement of the wiper linkage before fitting. This can help prevent the windscreen wiper motor from failing prematurely.

Note!

On febi bilstein wiper motors there are already threaded holes so that, using the supplied screws, mounting is trouble-free.

Register now for the official febi bilstein newsletter and receive the latest technical information automatically by email! Further information may be obtained at: www.febi.com

**Simply ask for spare parts by febi bilstein.
The complete range can be found at: www.febi-parts.com**