

Cost-effective repair solutions!

Do the ESP light or cornering lights not function as they should?

One cause of this can be a faulty steering angle sensor.



Note!

Steering angle sensors are not available separately from the manufacturer. In the past, if the sensor failed then it had to be replaced along with the whole jacket tube (Fig. 1).



Fig. 1

febi bilstein has the solution for a timely and efficient repair:

The steering angle sensor is now available separately!



febi no. 33745

Repl. no. 163 542 99 18

Suitable for Mercedes-Benz M Class (163)

Register now for febi bilstein's official newsletter and you will automatically receive the latest technical information by email! Further information may be obtained at: www.febi.com

Simply ask for spare parts by febi bilstein.
The complete range can be found at: www.febi-parts.com