

## Inoperable Citroen Xsara Picasso Column Switches after fitment

Part number: 251266, 251308, 251309,251492

For vehicle: Citroen Xsara Picasso models 2005 - 2011

To ensure the clock spring doesn't get damaged during installation of the column switch, please ensure that the below actions are carried out.

- Please ensure that the front wheels are set in " straight ahead position "
- On refitting the clock spring ensure that it's positioned in the 12 o'clock position in relation to the steering wheel.
- After refitting the steering wheel, start the vehicle and turn the steering wheel fully left and fully right until you reach the lock stops.

This simple process will avoid over - rotation of the clock spring and prevent damage.

In some instances (depending on the model) the column switch may have to be re-synchronised to the vehicle ECU. Please refer to the vehicle handbook or dealer if necessary.

***There is no need to replace a column switch until the above procedure has been checked.***