

Failure of wiper motor 579731 due to fuse overload

It has come to the attentions of Valeo Service that wiper motor 579731 is being replaced due to a failure that is in reality due to a fuse overload. This fault only occurs during colder temperatures when the windscreen wiper freezes to the windscreen. When the windscreen wiper is activated, the current consumed by the wiper motor increases to such a great extent that the 25 Amp fuse blows. To eliminate the fault please ensure that the wiper blade is in good condition and is not stuck to the windscreen prior to use. Before replacing the wiper motor please check the fuse and replace if necessary.

