Ref:Tech/013/03/06

## Important Service Bulletin

## 01/2006 GB

BIOIGIE

 $\boxtimes$  Workshop consulting  $\boxtimes$  Trade partners

☑ Quality engineering ☑ Workshop-partners

## Shock absorbers: BMW strut mount E36 / Z3 / Z4 87-386-A



## Part number concerned: 87-386-A

The damper mount on front axle was replaced on the BMW models E36 and Z3. In addition to the visual difference, a position pin is located at the upper attachment surface. This pin is needed only in the Z4 model. Therefore, it must always be removed in the models **E36 and Z3**.

Unscrew the position pin to remove it.

If the pin is not removed in the models E36 and Z3 fastening is impossible.