

Aluminium Wheel Cylinder

Product improvement of aluminium wheel cylinder range.

Due to our constant field observation we have found out that in very few cases while fitting Brake Shoes some dust caps were pushed from their seat. Water may penetrate in and could cause leakage of the wheel cylinder.

To improve the safety of the repair quality and to prevent that the dust caps are pushed from the seat during repair, we thickened the rubber of the dust cap (see picture) This ensures a stronger grip.

„Note: Following brake shoe or wheel cylinder replacement ensure all components are correctly positioned. Pay particular attention to wheel cylinder dust cover location.“

Improved parts are:

BWF145A, BWD113A, BWA108A, BWC107A, BWB111A and BWD119A

