PRODUCT NOTES

Application: BMW XDrive 4.4LP 2013 onwards

WHEN REPLACING THE REQUIRED TURBO, IT IS CRITICAL THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

• The production of turbo 840069-5015S will soon finish and it will be replaced by -840069-5018S. The new -5018S has a compressor outlet which is 4mm longer than the -5015S (see below). This means that to replace -5015S (or earlier dash numbers) it is necessary to also replace the compressor outlet hose. This part is currently only available through the Main Dealer.



