



VAG / Synchronous Drive / Service Interval.

GATES REFERENCE:

Multiple

MAKE:
MODEL:
MOTOR:
MOTOR CODE:

AUDI, SEAT, SKODA, VOLKSWAGEN
All
All
All



We notice many changes in the timing belt replacement intervals from the Volkswagen group, this info is shared via our website.

[Technical Bulletin 020 Addendum](#)

Please note that these replacement intervals are the OE recommendations for the maximum mileage of the drive.

A quicker change can be required when the car is used in adverse conditions, such as very sporty driving, extreme temperatures (*), sand and gravel, running a lot on idle speed (taxis, delivery vans etc), frequent stops, always driving short distances, etc. VAG therefore advises to check the condition of the components at every major service.

Do remember that the engine needs to be at room temperature before installation, and precise follow up of the OE installation recommendations is strongly advised.

We also recommend that you always check the latest OE information on replacement intervals.

(*) For prolonged exposure to temperatures above 26 °C or below -6 °C, the change interval is reduced from 5 to 4 years.

visit our web catalogue: <http://www.gatesautocat.com>

