

## Difficult gear selection and/or clutch pedal pulsates.

Seat Alhambra 1.9 TDi

Ford Galaxy 1.9 TDi

VW Sharan 1.9 TDi

If one of the above vehicles has a complaint of poor gear selection, clutch pedal pulsating and in extreme cases the pedal is drawn to the floor whilst driving the problem may lie in the gearbox.

If the vehicle suffers from the above problem it can sometimes be confused with a Dual Mass Flywheel problem.

With the gearbox removed check the input shaft for excessive movement. If movement is apparent the gearbox will need to be over hauled or replaced.