

Renault Megane I 633827




Our Precision, Your Advantage



KYB advises that the coil spring and top mount must be correctly aligned when assembling this shock absorber - otherwise you may hear noise whilst driving.

January 2018

Align bottom of coil spring with indent on spring seat



Align top of coil spring with indent in top mount



Check overall alignment of assembled unit

