


# TECHNICAL BULLETIN TB-55

Issue No. 01  
Date 23/07/07  
Author JH

It is possible that you were supplied with the Hitachi model as shown below for this application.

Although this unit appears to be different from the one removed from the vehicle, it is totally compatible and will interchange with the Bosch model below.

**BOSCH model**



**HITACHI model**

