

TECHNICAL BULLETIN TB-58

Issue No. 01
Date 27/06/07
Author DLB

Problems with the ignition switch and/or wiring harness on this application may cause the battery lamp not to extinguish completely (best visible in the dark), even when the generator is charging.

This problem may cause the battery to run empty.

Make sure to check the ignition switch and/or wiring harness.