

TECHNICAL BULLETIN TB-68

Issue No.01

Date 24/03/10

Author: PZs

Important installation instruction

Before building in the new starter to avoid it over cranking due to the switch, please check the ignition switch that it works well.