TECHNICAL BULLETIN TB-88

Issue No.01 Date 16/02/15 Author: PL

APPLICATION GUIDELINE FOR MERCEDES ATEGO STARTERS

MERCEDES uses 2 different suppliers for the starter of the OM904 and OM906 engines:

1. BOSCH: 0001231002, 0001231033 / 0986017240

MERCEDES: A0041518401, A0051512001, A0061512201, A0061512203

2. DELCO REMY: 8200138, 8200297

MERCEDES: A0061512101, A0061516701

Although the 2 starters look different from the outside, the DELCO REMY type can replace the BOSCH starter too after a thorough **ring gear inspection**.



If the ringgear is damaged: broken teeth or heavily worn tooth profile, the ring gear must be replaced with a new ringgear Mercedes: A3660320105.

If the ringgear inspection and change are not completed before the NEW 8200297 DELCO REMY starter installation, the starter will be out of warranty.