

Beep and Park technology evolution

Being one of the world leaders in OE and Aftermarket automotive technology Valeo is dedicated in improving its products to suit customer needs.

In 2016 Valeo enhanced the technology in the Beep and Park kit range to improve both the functionality of the kit and the aesthetics.

Please note to avoid confusion when ordering Beep and Park kits there has been no change in part numbers. However if spare parts are required, such as paintable sensors, new part numbers for the 2016 upgrade kits have been created.

The change in technology affects the following Beep and Park kits:

- 632000
- 632001
- 632002
- 632003
- 632004
- 632015



The below chart details the main differences between the two Beep and Park kits currently in circulation.

| 2011 > 11/2015 Version | 11/2015 > Version | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--|-------------|--------|------------------------------|--------|--------------------------|--------|---------------------|--------|------------------------|--------|--------------------|--------|----------------------------------|--------|---|--|----------|-------------|--------|------------------------------|--------|--------------------------|--------|---------------------|--------|------------------------|--------|--------------------|--------|----------------------------------|--------|---|
|  <p>10R-03 ECU Any ECU traceability codes between XX23024 and XX60122</p> |  <p>10R-05 ECU Any ECU traceability codes after XX61107 28% Smaller ECU for easier fitment</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|  <p>Rubber ring extra required if fitting to metal bumper</p>  <p>Angle on the angle rings of 6, 10 and 13 degrees (4 of each)</p>  <p>Sensors can't be painted . Sensors must be replaced by spare part 632114</p>  <p>Water droplet shaped sensor to allow water to run off</p> |  <p>No need for additional rubber rings: a rubber ring is integrated on the sensor by default</p>  <p>New angles on the angle rings of 0, 4 and 10 degrees (4 of each)</p>  <p>Sensors can't be painted . Sensors must be replaced by spare part 632214</p>  <p>Thinner and more discreet ring, due to the removal of the droplet and decreased depth</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>Pictograms on Packaging</p>  | <p>NEW Pictograms on Packaging</p>  | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <table border="1"> <thead> <tr> <th>2011>2015</th> <th>Spare Parts</th> </tr> </thead> <tbody> <tr> <td>632105</td> <td>spare sensor non shiny black</td> </tr> <tr> <td>632106</td> <td>spare sensor shiny black</td> </tr> <tr> <td>632107</td> <td>spare sensor silver</td> </tr> <tr> <td>632108</td> <td>spare sensor dark grey</td> </tr> <tr> <td>632109</td> <td>spare sensor white</td> </tr> <tr> <td>632114</td> <td>Spare part - paintable sensor x1</td> </tr> <tr> <td>632126</td> <td>Angle rings for beep&park sensors (x12)</td> </tr> </tbody> </table> | 2011>2015 | Spare Parts | 632105 | spare sensor non shiny black | 632106 | spare sensor shiny black | 632107 | spare sensor silver | 632108 | spare sensor dark grey | 632109 | spare sensor white | 632114 | Spare part - paintable sensor x1 | 632126 | Angle rings for beep&park sensors (x12) | <table border="1"> <thead> <tr> <th>From2015</th> <th>Spare Parts</th> </tr> </thead> <tbody> <tr> <td>632205</td> <td>spare sensor non shiny black</td> </tr> <tr> <td>632206</td> <td>spare sensor shiny black</td> </tr> <tr> <td>632207</td> <td>spare sensor silver</td> </tr> <tr> <td>632208</td> <td>spare sensor dark grey</td> </tr> <tr> <td>632209</td> <td>spare sensor white</td> </tr> <tr> <td>632214</td> <td>Spare part - paintable sensor x1</td> </tr> <tr> <td>632226</td> <td>Angle rings for beep&park sensors (x12)</td> </tr> </tbody> </table> | From2015 | Spare Parts | 632205 | spare sensor non shiny black | 632206 | spare sensor shiny black | 632207 | spare sensor silver | 632208 | spare sensor dark grey | 632209 | spare sensor white | 632214 | Spare part - paintable sensor x1 | 632226 | Angle rings for beep&park sensors (x12) |
| 2011>2015 | Spare Parts | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632105 | spare sensor non shiny black | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632106 | spare sensor shiny black | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632107 | spare sensor silver | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632108 | spare sensor dark grey | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632109 | spare sensor white | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632114 | Spare part - paintable sensor x1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632126 | Angle rings for beep&park sensors (x12) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| From2015 | Spare Parts | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632205 | spare sensor non shiny black | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632206 | spare sensor shiny black | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632207 | spare sensor silver | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632208 | spare sensor dark grey | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632209 | spare sensor white | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632214 | Spare part - paintable sensor x1 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 632226 | Angle rings for beep&park sensors (x12) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>Beepers and buzzers</p>  | <p>Beepers and buzzers are the same design</p>  | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

