

Technical Services Bulletin

The Problem

Valeo Warranty have had some beep and park kits returned due to problems with sensors not detecting objects or being too sensitive and activating the alert when there is no object in range. After inspecting the returned items it has come to light the sensors supplied in the kit have been painted.

The Valeo beep and park kits that include non-paintable sensors are:

| 632000 - Kit 1 | 632001 – Kit 2 | 632002 – Kit 3 |
|----------------|----------------|----------------------|
| 632003 – Kit 4 | 632004 – Kit 5 | 632015 – Kit 6 (LCV) |

The Cure

Valeo do not recommend the sensors supplied in the beep and park kits be painted as this can affect the sensitivity of the units.

If the user does wish to have the sensors painted to match the colour of their vehicle, specially designed, paintable sensors are available separately. They are listed with part number 632014.

Valeo warranty will not accept claims for beep and park kits when the sensors supplied have been painted.

Below are pictures of the different versions of sensors:



Parking sensor supplied in beep and park kits - Valeo **<u>DO NOT</u>** advise this version to be painted



632014 – Paintable sensor – Valeo only advise this sensor can be painted

valeo added[®]

T.S.B. No.: PE01/09

PRODUCT: Beep n Park

MARQUE: All makes

PART No.: 632000, 632001, 632002, 632003, 632004, 632015

SUBJECT: Sensors not detecting objects or being too sensitive

DATE: Aug 2009



www.valeoservice.co.uk





Enabling a better automotive world