

| Post Equipment | Beep and Park | Control Unit | All Makes

Beep and Park interference

When a beep and park kit is fitted to a vehicle, the unit can sometimes display faults or work erratically and the problem cannot be resolved when a replacement kit is used.

After investigation and testing on a vehicle with this particular issue, it has been found the Beep and Park control unit was experiencing some interference from another system fitted in the vehicle and the unit will need to be relocated or a shield fitted if relocation is difficult.



Valeo beep and park control unit



Units fitted in this area may be affected by interference

To test if a unit is experiencing interference, move the unit to another, temporary location away from any electrical units and check if the system is working correctly. This is to clarify there is not a fault with the beep and park kit.

If the unit is working correctly and does not experience the same faults, the unit will need to be relocated.

This issue is more likely to occur in newer vehicles when a control unit is fitted near a number of standard fit control units, in the vehicles front centre console for example.