
Damper element for rear light discontinued

Background

When the superior HD bulb began to be used in the rear lights it turned out that damper elements were no longer necessary.

Modification

The rear light damper element is discontinued in production and replaced by a spacer.

The new spacer is introduced as from the following chassis numbers:

Scania Södertälje	1 239 230
Scania Zwolle	4 391 402
Scania Angers	9 031 670
Scania Latin America	3 501 838

Parts

Designation	Part No. before change	Part No. after change
Damper element/ bracket	1 327 274	1 412 265