

Damper element for rear light discontinued

Background

When the superior HD bulb began to be used in the rear lights it turned out that damper elements were no longer necessary.

Modification

The rear light damper element is discontinued in production and replaced by a spacer.

The new spacer is introduced as from the following chassis numbers:

| | |
|-------------------------|-----------|
| Scania Södertälje | 1 239 230 |
| Scania Zwolle | 4 391 402 |
| Scania Angers | 9 031 670 |
| Scania Latin America | 3 501 838 |

Parts

| Designation | Part No. before change | Part No. after change |
|----------------------------|------------------------------|-----------------------------|
| Damper element/ bracket | 1 327 274 | 1 412 265 |