



All you need for professional repairs!

Control arm including fitting materials

febi no. 37000

Repl. no. 1 064 128 S1





Fits:

All models of the Ford Focus 1 (1998-2004) except for RS/ST170

Problems may arise when replacing the rear control arm (febi no. 32582) due to severe corrosion between the rubber mounts and the mounting bolts. Often the only way to sever the connection is by destroying the bolts. As a result, it is necessary to replace the nuts and bolts as well. However, the control arm is frequently supplied by the manufacturer without the necessary fitting materials.

febi bilstein has the solution for a timely and efficient repair:

febi bilstein now also supplies these control arms as a ProKit with the appropriate nuts and bolts (febi no. 37000).

This complete repair kit enables a professional repair without the need for additional sourcing trips. That saves time and money for both workshop and customer!



Note!

The eccentric bolt and eccentric washer are used to set the camber which is absolutely imperative after replacing the control arm.

Anyone using a ProKit can safely assume that it contains all the parts necessary for the repair. Discover the new complete repair kits at: www.febiprokit.com

Simply ask for spare parts by febi bilstein.
The complete range can be found at: www.febi.com

Ferdinand Bilstein GmbH + Co. KG

Wilhelmstr. 47 | 58256 Ennepetal | Germany

Tel. +49 2333 911-0 Fax +49 2333 911-444

