Valeo Tech Tips




Blower Motor 698263 Modification

Before fitting VAG blower motor 698263 the plug connection will need to be checked as an adapter may be required. If it is the original design being removed from the vehicle adapter 1J0-972-752 will need to be purchased from VW/Audi. Please see the images below to determine what design is being removed.



Original design





Wiping Systems

Clutches

Starters & Alternators

Braking Systems

Radiators & Intercoolers

Climate Control

Security Systems

Lighting Systems

Blower Motors

Fans

Switches

Window Lifts

Parking Sensor Kits

EGR Valves



valeo added IIIIIII

Original plug

www.valeoservice.co.uk



Valeo Tech Tips





Modified design



Modified plug



Wiping Systems

Clutches

Starters & Alternators

Braking Systems

Radiators & Intercoolers

Climate Control

Security Systems

Lighting Systems

Blower Motors

Fans

Switches

Window Lifts

Parking Sensor Kits

EGR Valves

Injectors

lanition

1J0-972-752 adapter that is required if replacing the original design with the modified design.





valeo added IIIIIII

www.valeoservice.co.uk

Valeo Service (UK) Ltd, Heming Road, Washford, Redditch, Worcestershire, B98 ODZ Tel: 01527 838300

Fax: 01527 523732

Automotive technology, naturally