

When it really matters: ABS components by febi bilstein

The anti-lock braking system (ABS) in vehicles is a long established driver assistance system. If there is potential for the wheels locking up, the ABS reduces the brake pressure, so that no wheel is locked and the braking process is stabilised.

If the ABS control lamp lights up while driving, this usually indicates a fault caused by defective components. Reasons may include damaged cables, corroded plug contacts, or damage to the impulse wheel.

Given that a defective anti-lock braking system compromises the proper function of the brake assistant, the brake force distribution and the electronic stability programme (ESP), the vehicle should be taken to a garage immediately, keeping a generous safety distance to any cars in front.


febi bilstein is not taking any chances, and provides suitable vehicle parts in tested OE matching quality.

ABS - sensor with sleeve and grease
febi no. 45825



to fit:
Mercedes-Benz Truck Atego I - II
Repl. no. 001 542 76 18

ABS - ring
febi no. 46762



to fit:
Mercedes-Benz Achsen BM 730
Repl. no. 975 334 05 15

Subject to technical changes

The complete range can be found at: www.trucks.febi-parts.com